

469

MYSORE DIVISION.

Dated 31st January 1905.

1. Notice is hereby given that sealed tenders will be received at the office of the Executive Engineer, Mysore Division, up to 20th February 1904 for restoring Kuthanur tank, Registered No. 22, Gundlupet. An approximate estimate of quantities is given below. These quantities are not guaranteed. The work should be completed by the end of May 1906.

2. The plans, detailed estimate and conditions may be seen at the Executive Engineer's office at Mysore between the hours of 11 A.M. and 5 P.M.

3. Tenders should be submitted on printed forms which may be obtained from the Executive Engineer. The tenders should be accompanied by a statement in the form given below, showing the rates at which the different items specified will be executed.

4. Each tender must be accompanied by a deposit of rupees two hundred in cash or Government Promissory Notes, as earnest money, and be superscribed "Tender for restoring Kuthanur tank, Registered No. 22, Gundlupet," in default of which, tenders will be rejected.

5. The final acceptance of any tender will rest with the Superintending Engineer, who does not bind himself to accept the lowest or any tender or to assign any reason whatever for the rejection of any tender.

6. Within eight days of the acceptance of the tender, the successful competitor will be required to execute the usual contract bond; in default of which, his tender will be considered cancelled, and his earnest money will be forfeited.

7. The name of the successful competitor, whose tender has been accepted, will be posted on the notice board in the Executive Engineer's office in due course. No enquiries regarding the acceptance or rejection of a tender will receive any reply.

8. On acceptance of one of the tenders, the earnest money on rejected tenders will be returned.

Bund—

Earthwork	C. yd.	3,960
Turfing slopes	S. yd.	2,140
New stone-work	C. yd.	4,006
Gravel backing	"	984
Old stone work	C. yd.	342
Register No. stone	No.	1
B. M. stones	No.	2
Gauge stone	No.	1
Old grade stones removing and refixing with new bed stones	No.	38
Index stones new	No.	38

Repairing sluice—

Examining and repairing sluice	Lump sum
--------------------------------	-----	-----	-----	----------

Left waste-weir 285'—

Earthwork	C. yd.	353
Brick in surki mortar	{C. ft.	1,998
Stone slabs (dressed)	S. ft.	707
Plastering with surki mortar	Sqr.	17.58
Rough stone work new	C. yd.	284
Benching rock	L S	
Cutting the draft in front of weir	L S	
Jungle clearing, &c.	L S	

V. ARUNACHELLAM, Executive Engineer.